

# IPHA TECHNICAL SEMINAR 2017

October 25–26. Tallinn, Estonia

## Design aspects of finished elements

**Jaime Fernández Gómez**

Technical University of Madrid/SEG | Spain



Organized by



INTERNATIONAL PRESTRESSED  
HOLLOWCORE ASSOCIATION

in cooperation with



supported by



sored by



# Design Aspects of Finished Elements



Prof. Jaime Fernández-Gómez

Full Professor on Building Construction and Prefabrication. Polytechnic University of Madrid. Vice-Chairman of SEG

# Content

1. Quality control as a tool to avoid defects
2. Dimensional tolerances
3. Slippage of prestressing tendons
4. Treatment of imperfections
  - Safety
  - Constructional purposes
  - Aesthetics
5. Full-scale loading tests

# 1. Quality control system

- It must include all activities
- Accepted by Manager
- Carried out by personnel not involved in production
- Written programme
- Need for continuous improvement
- Need to be realistic

# Quality control programme

- Organization chart and relations among personnel
- Monitoring by the management. Annual revision
- Equipment
- Procedures:
  - Purchases
  - Calibration
  - Inspection reports
  - Reports
  - Production
  - Tolerances
  - Erection
- Treatment of deviations

# Written procedures

- Material receipt
- Sampling and testing
- Drawings: checking and approval
- Product checking
- Production, storage and transportation
- Prestressing
- Mix design
- Concrete sampling and testing
- Final inspection of finished products
- Repair of non-conforming products
- Record of quality control operations
- Equipment maintenance and calibration

# Inspections

- Constituent materials and products
- Moulds
- Reinforcing
- Tensioning and detensioning
- Concreting and curing
- Demoulding and storage
- Finished products
- Final record of products



# Example of quality control procedures

Automatic prestressing. In this case, 13 Tn.

The jack stops at specified load, and does not allow a different one to be applied





# Checking the prestressing load by calibrated gauges




# General inspection before concreting






# Checking prestressing on strand



# Checking the reinforcement position in several sections along the length






Concreting. Checking the operations



# Automatic laser marking






After concreting, checking dimensions in several sections along the length





After concreting, checking dimensions in several sections along the length





## Identification and capping the end of the cores




# Concrete assesment. Specimens

- Use of cubic specimens or cylinders with polishing capping
- Equivalent coefficients to transform cube strength in cylinder strength





Construction drawing with adjustment area. Definition of element, number and lorry identification  
Layout thought for opening big holes in the future



# Building situation



To open big holes in  
the future



## 2. Dimensional tolerances

- Two types of tolerances:
  - Manufacturing tolerances, depending on manufacturing processes (length, width, among others)
  - Building tolerances, associated with incorporating the components into the building structure (dimensions between supports, support length, among others)
- Manufacturing tolerances are divided into structural and non-structural




# Practical application of tolerance systems

- Existence of good manuals of tolerances
  - PCI, ACI
- EN standards do not define acceptance criteria
- Need for good judgement and practical experience
- In many cases, tolerances defined in projects are extremely difficult to comply with
- There is no need for stricter tolerances than actually needed
- Look at the problem, taking into account the overall effect on construction



# Example of building tolerances



# Dimensional Tolerances

Item		Minimum	Maximum	Remark
Length ( $L$ )		- 25 mm	+25 mm	
Width ( $b$ )	Whole slab	- 5 mm	+5 mm	
	Narrowed slab	-25 mm	+25 mm	
Slab depth ( $h$ )	$h \leq 150$ mm	- 5 mm	+10 mm	The slab height has a direct influence on the flexural and the shear capacity of the slab
	$150 < h < 400$ mm	Linear interpolation		
	$h \geq 400$ mm	- 10 mm	+15 mm	
Min. web thickness ( $b_w$ )	Individual web	- 10 mm		The web thickness is influencing the shear and torsion resistance of the slab
	Total per slab	- 20 mm		
Minimum flange thickness (above and underneath the cores) ( $f$ )	Individual flange	- 10 mm	+ 15 mm	The flange thickness is influencing the resistance against fire, torsion and point loads
	Average flange	- 5 mm		

# Dimensional Tolerances

Item		Minimum	Maximum	Remark
Position of prestressing tendons (c)	$h \leq 150$ mm	- 5 mm	+ 5 mm	Furthermore, requirements on minimum cover should be respected
	$150 < h < 400$ mm	Linear interpolation		
	$h \geq 400$ mm	- 10 mm	+10 mm	
	Centre of gravity for total slab	-5 mm	+8 mm	
Minimum support length ( $l_s$ )	$h < 400$ mm	60 mm		Will be dependent on building tolerances
	$h \geq 400$ mm	80 mm		
Orthogonality (g)		-10 mm	+10 mm	Deviation from orthogonality of slab
Sweep (s)	$L \leq 12$ m	-5 mm	+5 mm	
	$L > 12$ m	-10 mm	+10 mm	
Openings, block- outs	Location in fresh concrete	-25 mm	+25 mm	
	Location in hardened concrete	-15 mm	+15 mm	
	Size in fresh concrete	-20 mm	+50 mm	
	Size in hardened concrete	-20 mm	+30 mm	

# Slippage of prestressing tendons

- Example:
  - 12.5 mm diameter strand
  - $l_{pt2} = 50 \varnothing$
  - Prestressing stress: 1177 N/mm<sup>2</sup>
  - $\Delta l_0 = 1.5$  mm
- Knowing the slippage,  $l_{pt2}$  can be calculated
- Shear capacity can be assessed

$$- V_{Rd,c} = \frac{l \cdot b_w}{s} \sqrt{(f_{ctd})^2 + \frac{l_x}{l_{pt2}} \sigma_{cp} f_{ctd}}$$

# 3. Slippage of prestressing tendons

- Relation with transmission length
- Maximum allowable bond slip should be considered in assessing the shear capacity
- Strand slippage
  - $\Delta l_0 = \beta l_{pt_2} * \frac{\sigma_{p0}}{E_p}$
  - $\beta$  = Prestress coefficient  $\approx 0,4$
  - $l_{pt_2}$  = upper bound value of transmission length
  - $\sigma_{p0}$  = prestressing stress immediately after release
  - $E_p$  = modulus of elasticity
- Limit values given in EN 13369
  - Individual tendons =  $1,30 \Delta l_0$
  - Mean value of all tendons =  $1,0 \Delta l_0$

# Slippage of prestressing tendons

- First check may be performed visually
- If needed, check the slippage of each strand



# 4. TREATMENT OF IMPERFECTIONS

Task Group 6.8 of FIB Commission 6 Prefabrication  
“Treatment of Imperfections in precast concrete structural  
elements”


- Convener
  - José Calavera, Spain
- Members
  - Kamel Bensalem, England
  - Sébastien Bernardi, France
  - Barry C. Crisp, Australia
  - Jaime Fernández, Spain
  - David Fernández-Ordóñez, Spain
  - Nordy Robens, Belgium
  - Aarto Suikka, Finland (†)
  - Arnold van Acker, Belgium
  - Aad van Paassen, The Netherlands





# Acceptance and rejection

- Difficulties of rejection precast structural elements
  - Economic importance of units
  - Problems of delivery and delays
- Difficulties in analysing flaws in ways not normally addressed in technical codes
- To establish routine procedures (production and acceptance) for handling defects



# Scope of FIB Document

- Evaluation of imperfection of precast concrete elements that do not meet the quality intended in design
- Provision of rules and possible evaluation systems
- Recommendations for the following
  - Prevention
  - The effect the imperfections can have
  - Actions for rectification
- The document should be read in conjunction with relevant codes and standards

# Types of Defects

- Dimensional deviations
- Surface and aesthetics
- Surface flatness
- Colour and Colour variations
- Cracking
- Deflection and Camber
- Cracks
- Spalling, splitting and bursting
- Accidental damage

# Segregation





# Casting problems



Longitudinal crack above core





Problems in adjustment area. Different possibilities of solution. Relation with design





Storage stains.

Clean with pressured water on site



# Wire slipping





# Transference cracks



# Accidental damages





Colour defects. Hollow cores used as panels





# General cracks

- Inherent in reinforced concrete
- Different causes
  - Thermal cracks
  - Plastic settlement and autogenous shrinkage
  - Drying shrinkage
  - Mechanical cracks
    - Handling problems
    - Spalling, splitting and bursting
    - Due to stresses
- Always analyse the consequences in safety and durability. Example about how to evaluate safety included in the appendix of the FIB document



# Maximum size and amount of visual cracks in concrete surfaces

Surface treatment	Class AA	Class A
Light mould surface, steel rubbed, fine washed aggregate, low sand blast or acid treated surface	not allowed	0,1 / 500
Dark mould surface, timber rubbed, brushed or medium sandblasted surface	0,1 / 500	0,2 / 500 0,1 / 1000
Washed aggregate or deep sandblasted surface	0,2 / 500	0,2 / 1000
<b>Coated surfaces</b>		
Inside structure		0,2 / 1000 0,1 / 5000
Outside structure		0,3 / 3000 0,2 / 5000

# Grey colour classification according to CIB report N° 24







15 cm



## Hollowcore prices

Price (€/m <sup>2</sup> )		Depth (cm)
Manufacturing	Total ( 200 Km )	
27	33	20
65	80	50

## Crack injection prices

Price (€/m)		Equipment displacement
Preparation	Injection + material	
42	55	300

## Pressured hydrocleaning

Price (€/m <sup>2</sup> )	
Cleaning	Equipment displacement
10	500

# Practical application of repair decisions

- A normal unit (10 m<sup>2</sup>) costs €270-650
- Do not take risks in relation with safety
- A repair must be something simple, easy and inexpensive, and one that solves the problem
- Aesthetical repairs can be performed onsite, taking into account the general problem
- Longitudinal cutting, in order to obtain a small unit, can be a general procedure for not acceptable elements
- Injecting cracks properly is a specialized work and quite expensive for small units

# Cleaning with pressured water on site





## Defect and repair in adjustment area



## Longitudinal cutting repair





Cutting and changing the length for other uses





Specific cases




Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="224 199 582 231"><b>Longitudinal cracks at the web</b></p> 	<p data-bbox="638 199 918 231"><b>A) Improper production</b></p> <p data-bbox="638 239 896 271">Subsidence over cores.</p> <p data-bbox="638 359 952 391">Excess water in the concrete.</p> <p data-bbox="638 438 884 470">Heat applied too early.</p> <p data-bbox="638 566 929 638">Shrinkage due to improper curing and mix proportions.</p> <p data-bbox="638 686 952 718">Excess water in the concrete.</p> <p data-bbox="638 766 862 798">Rapid moisture loss.</p> <p data-bbox="638 1013 884 1045">Heat applied too early.</p> <p data-bbox="638 1133 963 1165">Excessive curing temperature.</p> <p data-bbox="638 1212 840 1244">Differential curing.</p>	<p data-bbox="996 239 1332 271">Prevent subsidence over cores.</p> <p data-bbox="996 359 1232 391">Reduce water content.</p> <p data-bbox="996 438 1310 510">Delay bleeding of rubber void forms.</p> <p data-bbox="996 566 1332 638">Improve curing procedures and mix.</p> <p data-bbox="996 686 1232 718">Reduce water content.</p> <p data-bbox="996 766 1355 917">Cover product as soon as possible after casting. In extreme cases spray product with mist or curing compound before covering.</p> <p data-bbox="996 1013 1355 1085">Increase preset time before curing temperature rise begins.</p> <p data-bbox="996 1133 1299 1165">Reduce curing temperatures.</p> <p data-bbox="996 1212 1254 1332">Check for uneven curing temperatures and make appropriate corrections.</p>	<p data-bbox="1377 239 1713 438">Minor cracking should have little effect, however, it may create problems with concentrate load distribution in slabs without concrete topping.</p>	<p data-bbox="1736 239 2016 518">If the crack is severe, concrete slab may be cut along its length and used as narrow width units or may be used in conjunction with a concrete topping.</p>


Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="226 167 443 199"><b>Transverse cracks</b></p> 	<p data-bbox="589 167 808 199"><b>A) Improper design</b></p> <p data-bbox="589 228 875 260">Excessive top fibre tension.</p> <p data-bbox="589 300 848 368">Inadequate or misplaced cantilever reinforcement.</p> <p data-bbox="589 432 860 464"><b>B) Improper production</b></p> <p data-bbox="589 515 831 547">Longitudinal shrinkage.</p> <p data-bbox="589 603 887 635">Excessive water in concrete.</p> <p data-bbox="589 738 826 770">Heat applied too early.</p> <p data-bbox="589 874 909 906">Excessive curing temperature.</p> <p data-bbox="589 962 943 1031">Uneven heating along the casting bed.</p> <p data-bbox="589 1054 909 1123">Contraction due to delayed detensioning of cured product.</p> <p data-bbox="589 1198 808 1230">Low release strength</p> <p data-bbox="589 1286 833 1318"><b>C) Improper handling</b></p> <p data-bbox="589 1374 786 1406">Cantilever loading.</p>	<p data-bbox="963 228 1227 260">Reduce top fibre tension.</p> <p data-bbox="963 300 1294 368">Use adequate reinforcement at proper position.</p> <p data-bbox="963 515 1279 547">Proper mix design and curing.</p> <p data-bbox="963 603 1312 715">Reduce water content. Cover product as soon as possible after casting.</p> <p data-bbox="963 738 1290 807">Increase preset time before curing temperature rise begins.</p> <p data-bbox="963 874 1256 906">Reduce curing temperature.</p> <p data-bbox="963 962 1294 994">Check heat distribution system.</p> <p data-bbox="963 1054 1317 1166">Detension as soon as the release strength is reached, before the product cools.</p> <p data-bbox="963 1198 1256 1267">Increase release strength to accommodate top tension</p> <p data-bbox="963 1374 1234 1442">Allow adequate cantilever position.</p>	<p data-bbox="1337 167 1637 523">Potential shear capacity reduction if crack occurs at end. Can have significant effect on shear and moment capacities of cantilevers. Reduction of moment inertia in centre of member can cause differential camber and excessive deflection.</p>	<p data-bbox="1662 167 2020 320">For minor cracks epoxy can be effective, and filling the core solid at the crack position can enhance shear capacity.</p> <p data-bbox="1662 331 2020 443">Minor cracks in the top flange at areas of positive moment may not require any repair.</p> <p data-bbox="1662 454 2020 646">When a severe crack occurs in a member, the cracked section should be cut and rejected and the remaining length reclaimed and placed in the stock.</p>

Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<b>Longitudinal cracks over the cores</b>	<b>A) Improper design</b>			
	Eccentricity of prestressing steel	Design with even distribution of steel.	Cracks can affect the load distribution in slabs without concrete topping.	Filling the core solid can repair these cracks.
	<b>B) Improper production</b>		These can also have an effect on slabs with openings or transverse cantilevers.	For slabs and beams used in conjunction with a concrete topping, repair may not be required.
	Transverse shrinkage	Proper mix design and curing.		When a severe crack occurs in a member, the cracked section should be cut and rejected and the remaining length reclaimed and placed in the stock.
	Excessive water in concrete.	Reduce water content.		
	Rapid loss of moisture.	Cover product as soon as possible after casting. In extreme cases spray product with mist or curing compound before covering.		
	Heat applied too early.	Increase preset time before curing temperature rise begins.		
	Excessive curing temperature.	Reduce curing temperature.		
	Different curing temperatures at each side.	Check for uneven curing temperatures and make appropriate corrections.		
	Diferencial compaction.	Improve vibration.		
	Steel displaced during casting.	Prevent displacement of steel.		
Improper cutting sequence.	Cut steel from centre to outside.			
Flange too thin due to movement or misalignment of voids.	Correct and maintain core positions.			
Over-inflation of void formers.	Maintain proper inflation.			
<b>C) Improper handling and storage</b>				
Handling problems.	Use appropriate method of handling.			
Uneven stacking.	Provide uniform bearing.			
Settlement of the stack.	Put heavier product at bottom of stack and reduce stack height.			


Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="212 183 555 255"><b>Longitudinal web cracks at or near the strand</b></p> 	<p data-bbox="582 183 806 215"><b>A) Improper design</b></p> <p data-bbox="582 263 884 295">Excessive bursting stresses.</p> <p data-bbox="582 359 896 430">Web not thick enough for the prestress force.</p> <p data-bbox="582 462 940 534">Strand diameter too large for thin web</p> <p data-bbox="582 582 862 614"><b>B) Improper production</b></p> <p data-bbox="582 678 929 750">Lateral strand movement during casting.</p> <p data-bbox="582 782 817 813">Low release strength.</p> <p data-bbox="582 901 896 973">Lack of concrete compaction around the strands.</p> <p data-bbox="582 1021 918 1053">Layers of concrete not bonded.</p> <p data-bbox="582 1157 929 1228">Saw-cut not deep enough or not complete across the sides.</p> <p data-bbox="582 1284 840 1316"><b>C) Improper handling</b></p> <p data-bbox="582 1364 929 1436">Uneven handling due to picking devices not being level.</p>	<p data-bbox="963 263 1243 295">Reduce bursting stresses.</p> <p data-bbox="963 359 1243 430">Increase web thickness if possible.</p> <p data-bbox="963 462 1321 534">Provide equivalent prestress with smaller diameter strand.</p> <p data-bbox="963 678 1299 750">Check strand guides on casting machine.</p> <p data-bbox="963 782 1243 813">Increase release strength.</p> <p data-bbox="963 901 1288 933">Improve concrete compaction.</p> <p data-bbox="963 1021 1310 1093">Revise production procedures to avoid cold joints.</p> <p data-bbox="963 1157 1265 1228">Saw completely through the section of the member.</p> <p data-bbox="963 1364 1321 1436">Use spreader beams to minimise uneven handling.</p>	<p data-bbox="1344 183 1646 335">These cracks can reduce the shear capacity because effective and undamaged webs resist the shear stress.</p> <p data-bbox="1344 351 1646 462">Evaluate a shear capacity reduction similar to members with openings near the end.</p>	<p data-bbox="1668 183 2016 335">The repair of these cracks is dependent on the shear requirements. The cores can be filled solid.</p> <p data-bbox="1668 351 2027 542">When a severe crack occurs in a member, the cracked section should be cut and rejected and the remaining length reclaimed and placed in the stock.</p>



Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="212 229 479 300"><b>Cracks at corner of the member</b></p> 	<p data-bbox="584 229 860 261"><b>A) Improper production</b></p>			
	<p data-bbox="584 322 943 386">Saw blade pinches when member cambers.</p>	<p data-bbox="965 322 1256 386">Place weight on member to restrict camber.</p>	<p data-bbox="1344 229 1644 386">The effect of these cracks is usually minimal but can reduce the shear capacity if the webs are damaged.</p>	<p data-bbox="1673 229 2029 421">The repair of these cracks is dependent on the shear requirements. Epoxy resin can be used and the cores can be filled solid.</p>
	<p data-bbox="584 443 913 507">Saw cut not deep enough or wobbles due to excessive use.</p>	<p data-bbox="965 443 1312 593">Cut completely through the strands and as close as possible to the bottom of the member and use a properly maintained saw,</p>	<p data-bbox="1344 395 1644 507">Evaluate a shear capacity reduction similar to members with openings near the end.</p>	<p data-bbox="1673 434 2018 625">When a severe crack occurs in a member, the cracked section should be cut and rejected and the remaining length reclaimed and placed in the stock.</p>
	<p data-bbox="584 536 920 600">Excessive tension stress during stripping.</p>	<p data-bbox="965 536 1312 593">Employ proper cutting sequence.</p>	<p data-bbox="1344 513 1644 663">If the damage is severe, cut and reject the end of the member and use the remaining of the length.</p>	
	<p data-bbox="584 912 882 983"><b>B) Improper handling and storage</b></p> <p data-bbox="584 1034 770 1066">Uneven stacking.</p> <p data-bbox="584 1168 920 1232">Uneven handling to due picking devices not being level.</p> <p data-bbox="584 1334 860 1366">Damage during transport.</p>	<p data-bbox="965 746 1312 778">Employ proper cutting sequence.</p> <p data-bbox="965 1034 1312 1066">Provide level bearing in the stack.</p> <p data-bbox="965 1168 1312 1232">Use spreader beams to minimise uneven handling.</p> <p data-bbox="965 1334 1256 1404">Ensure good transport procedures are adhered to.</p>		

Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="226 209 566 279"><b>Cracks in the web above the strand</b></p> 	<p data-bbox="589 209 817 240"><b>A) Improper design</b></p> <p data-bbox="589 296 904 405">Excessive prestress force in relation to the cross sectional area of concrete.</p> <p data-bbox="589 708 866 740"><b>B) Improper production</b></p> <p data-bbox="589 791 891 823">Insufficient release strength,</p> <p data-bbox="589 884 878 992">Bottom surface of member sticking to the bed during stripping.</p> <p data-bbox="589 1037 871 1069">Saw cut not deep enough.</p> <p data-bbox="589 1228 831 1260">Mix too wet or too dry.</p> <p data-bbox="589 1366 808 1398">Insufficient vibration.</p>	<p data-bbox="963 296 1312 488">Reduce shear lag through webs. Increase web width. Add top strand. Reinforce webs Reduce prestress force.</p> <p data-bbox="963 791 1240 823">Increase release strength.</p> <p data-bbox="963 884 1305 992">Clean and oil casting bed properly or ensure a dry contact surface.</p> <p data-bbox="963 1037 1312 1145">Cut completely through the strands and as close as possible to the bottom of the member.</p> <p data-bbox="963 1228 1247 1260">Adjust the mix accordingly.</p> <p data-bbox="963 1366 1196 1439">Improve vibration and compaction.</p>	<p data-bbox="1337 209 1641 560">These cracks can reduce the shear capacity because effective and undamaged webs resist the shear stress. The design shear capacity should be reduced and conservative to make allowance for the damaged webs.</p>	<p data-bbox="1659 209 1986 320">The shear capacity may be enhanced by filling solid cores where the webs are damaged.</p>

Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<b>Accidental cracks</b>	<b>A) Improper handling and storage</b>			
	Transport over uneven ground.	Transport product over a well defined even ground.	Depending on their location and severity, these cracks can have significant effect on the slabs capacity.	If large pieces of concrete have been removed these can be replaced with fresh and well compacted concrete, provided the slab is adequate without the repair.
	Product transported at high speed.	Transport product at reasonable speed.	Evaluate the severity of the damage on the bending and/or the shear capacity.	Cracks can be repaired with Epoxy resin or concrete mortar.
	Improper transport machinery.	Use only appropriate machinery for transporting the product.	Work out the residual capacity of the damaged slab prior to repairs and check to see if this is adequate.	Where a severe damage occurs in a localised area of a member, the damaged area should be cut and rejected and the remaining length reclaimed and placed in the stock.
	Lack of training.	Train the personnel involved in transporting and stacking the product.	If the residual capacity is adequate proceed with the repairs, if not either reject the member or cut and reject the damaged area.	
	Stacking in uneven ground.	Stack product only on even ground.		
	Misplaced bearers.	Bearers should be placed at the right places and should be of the right size and shape.		
	Products with different sizes and shapes.	Each stack should only have products with similar size. Do not exceed the maximum number of rows permitted.		

Typical case (hollow cores)	Cause	Prevention	Effect	Repair
<p data-bbox="215 196 557 268"><b>Imperfections in holes, recesses or lifting devices</b></p> 	<p data-bbox="584 204 842 276"><b>A) Improper design or production</b></p> <p data-bbox="584 292 904 323">Lack of dug holes or recesses</p> <p data-bbox="584 515 801 547">Lack of lifting hooks.</p> <p data-bbox="584 730 898 802">Lack of intermediate webs or other strengthening for lifting.</p> <p data-bbox="584 1002 891 1074">Lack of drilled water holes in lower flange.</p> <p data-bbox="584 1273 880 1345">Lack of plugs or other filling material for core ends.</p>	<p data-bbox="927 292 1267 443">Improved data transfer at stage of design and manufacture and improved quality control of production</p>	<p data-bbox="1290 292 1630 403">Joints cannot be finished and installations of piping cannot be done.</p> <p data-bbox="1290 515 1592 547">Lifting difficult or dangerous.</p> <p data-bbox="1290 1002 1608 1074">Rainwater can gather into the cores during construction.</p> <p data-bbox="1290 1273 1619 1345">Additional use of joint cast. Deadweight of slabs increases.</p>	<p data-bbox="1653 292 1989 403">Recess shall be made carefully on site. Small holes are drilled and big holes cut on site.</p> <p data-bbox="1653 515 1962 587">Lifting are made with special equipment.</p> <p data-bbox="1653 730 1962 802">Lifting are made with special equipment.</p> <p data-bbox="1653 1002 1984 1034">Water holes are drilled on site.</p> <p data-bbox="1653 1273 2000 1385">Cores are plugged or ends filled with other methods before joint cast.</p>



# 5. Full scale loading tests


- For product family, at the beginning of production as acceptance test. At least three units
- During production as quality control test:
  - Every 3-6 months
  - Per type of slab each 25,000-50,000 m<sup>2</sup>
- Shear test
- Flexural test
- Loading procedure
  - First cycle: 35% expected failure  $F_{cal}$
  - Second cycle: 50%  $F_{cal}$ , 75%  $F_{cal}$ , and up to failure
- Initial type testing:
  - $F_{test} / F_{cal} \geq 0.95$  for each test
  - $F_{test} / F_{cal} \geq 1.00$  average value of three tests

Flexural test. No need to break the unit, once the maximum load is reached and the deflection increases without increasing the load.

Possible problems with the jack



Shear test. Length of the slab at least 4.0 m or 12 h



## Shear test





Thank you for your attention

